

Award Bios Setup (2C4I9F21)

	TYPE	SIZE	CYLS	HEAD	PRECOMP	LANDZ	SECTOR	MODE
Drive C :	User	1705Mb	3305	16	0	3305	63	Normal
Drive D :	None	0Mb	0	0	0	0	0	-----
Drive A	:	None						
Drive B	:	1.44M, 3.5 in.						
Floppy 3 Mode	:	Disabled						
Video	:	EGA / VGA						
Halt On	:	All Errors						

BIOS FEATURES SETUP

Virus Warning	:	Disabled	Video BIOS Shadow	:	Enabled
Internal Cache	:	Enabled	C8000-CFFFF Shadow	:	Disabled
External Cache	:	Enabled	D0000-D7FFF Shadow	:	Disabled
Quick Power On Self Test	:	Enabled	D8000-DFFFF Shadow	:	Disabled
Boot Up Sequence	:	C, A			
Boot up Floppy seek	:	Disabled			
Boot up NumLock Status	:	On			
IDE HDD Block Mode	:	Disable			
Gate A20 Option	:	Fast			
Typematic Rate Setting	:	Enabled			
Typematic Rate (Chars/Sec)	:	6			
Typematic Delay (Msec)	:	250			
Password Option	:	Setup			

CHIPSET FEATURES SETUP

Auto Configuration	:	Disable	Latch Local Buss	:	T3
AT Bus Clock	:	1/4 CLKIN	Local Buss Ready	:	Synchronize
DRAM Speed	:	Faster			
DRAM Write WS	:	1 WS	Memory Hole Size	:	None
DRAM Write to CAS	:	1T			
DRAM Write Burst	:	Disabled	DMA Clock	:	4Mhz
Slow Refresh	:	Disabled			
External Cache	:	WB			
Cache Burst Read	:	2T			
Cache Write Cycle	:	2T			
System Shadow	:	Cacheable			
Video Shadow	:	Cacheable			

POWER MANAGEMENT

Power Management	:	Disabled
ALL OTHERS	:	Disregard