

Award Bios Setup (2A59IO09) PCI Pentium

HARD DISKS	TYPE	SIZE	CYLS	HEAD	PRECOMP	LANDZ	SECTOR	MODE
Primary Master	: Auto	0	0	0	0	0	0	Auto
Primary Slave	: None	0	0	0	0	0	0	-----
Secondary Master	: None	0	0	0	0	0	0	-----
Secondary Slave	: None	0	0	0	0	0	0	-----

Drive A : None
Drive B : 1.44M, 3.5 in.

Video : EGA/VGA
Halt On : All Errors

BIOS FEATURES SETUP

Virus Warning	: Disabled	Video BIOS Shadow	: Enabled
CPU Internal Cache	: Enabled	C8000-CBFFF Shadow	: Disabled
External Cache	: Enabled	CC000-CFFFF shadow	: Disabled
		D0000-D3FFF Shadow	: Disabled
Quick Power On Self Test	: Enabled	D4000-D7FFF Shadow	: Disabled
Boot Sequence	: C only	D8000-DBFFF Shadow	: Disabled
Swap Floppy Drive	: Disabled	DC000-DFFFF Shadow	: Disabled
Boot up Floppy Drive	: Disabled		
Boot up Num Lock	: On		
Boot up System Speed	: High		
Typematic Rate Setting	: Disabled		
Typematic Rate (Chars/Sec)	: 6		
Typematic Delay (Msec)	: 250		
Security Option	: Setup		
PCI/VGA Palette Snoop	: Disabled		
OS Select For DRAM > 64 MB	: Non-OS2		
Report No FDD for WIN 95	: No		

CHIPSET FEATURES SETUP

Auto Configuration	: Disable		
DRAM Leadoff Timing	: 10 / 6 / 4	10 / 6 / 3	
DRAM Read Burst (EDO/FP)	: x333 / x444	x222 / x333	
DRAM Write Burst Timing	: x333	x222	

Fast EDO Lead Off	: Disabled		
Refresh RAS# Assertion	: 5 CLKS	4 CLKS	
Fast RAS to CAS Delay	: 3	2	
DRAM Page Idle Timer	: 2 CLKS		
DRAM Enhanced Paging	: Enabled		
Fast MA to RAS # Delay	: 2 CLKS		
SDRAM (CAS Lat/RAS-to-CAS)	: 3/3		
SDRAM Speculative Read	: Disabled		
System BIOS Cacheable	: Enabled	Disabled	
Video BIOS Cacheable	: Enabled		
8 Bit I/O Recovery Time	: 1		
16 Bit I/O Recovery Time	: 2		
Memory Hole at 15M-16M	: Disabled		
PCI 2.1 Compliance	: Enable		

PNP/PCI Configuration

PNP OS Installed	: No	PCI IDE IRQ Map To	: PCI Auto
Resources Controlled By	: Auto	Primary IDE INT #	: A
Reset Configuration Data	: Disabled	Secondary IDE INT #	: B

Integrated Peripherals

IDE HDD Block Mode	: Disabled		
IDE Primary Master PIO	: Auto		
IDE Primary Slave PIO	: Auto		

IDE Primary Master UDMA	: Auto	Disable	
IDE Primary Slave UDMA	: Auto	Disable	
IDE Secondary Master UDMA	: Auto	Disable	
IDE Secondary Slave UDMA	: Auto	Disable	
On-Chip Primary PCI IDE	: Enabled		
On-Chip Secondary PCI IDE	: Disabled		
KBC Input Clock	: 8 MHz		
OnBoard FDD Controller	: Enabled		
OnBoard Serial Port 1	: 3F8/IRQ4		
OnBoard Serial Port 2	: Disabled		
OnBoard Parallel Port	: 378/IRQ		
ParallelPort Mode	: SPP	Normal	
USB Keyboard Support	: Disabled		